

INCIDENT ALERT

	General Information			
	Date of Incident	26/10/2013		
	State	Qld		
	Type of Incident	Incident Causing Injury (No Lost Time)		
		About the Person		
	Occupation of Person	HPWJ operator		
	Experience of Person	12 - 24 months	7	
	Training Level	Company Induction		
	Other Training	Industrial Services Induction		
	No. of Hours Completed	0 – 2 hours		
	About the Incident			
	Time of Accident	17:15pm		
	Result of Injury	Doctor Only		
	Lost Days	Nil		
	Description of	Graze to hand		
	Incident	Graze to Haria		
	What Equipment Category	Purpose Built Equipment		
	Equipment Used	Peinemann LTC and flex lance	2	
	What happened unexpectedly	The flex lance looped from a gap between the tube and the end of the Peinemann LTC		
	What Was Person Doing	Cleaning tubes	1	
	Corrective Action			
		Immediate releasing of the hold to activate device Activation of the E stop.		
	What Immediate Action	Reporting of incident to company and client.	8	
		Medical attention	9	
		Incident investigation started.		
	Preventative Action			
	Elimination			
	Substitution		1	
	Isolation or barriers			
		Fixed mechanical holding device sourced to hold the		
	Engineering	Peinemann close to the tube to stop side way movement of		
		the flex lance.		
	Administration	An investigation was conducted and an internal safety alert issued.		
	PPE			
•	(I	LEADAUNGO	_	

LEARNINGS

Operators of specialised items of equipment such as the Peinemann LTC must be trained and competent in their correct and safe use.

The risk assessment process (JSEA or similar) carried out prior to the work commencing must consider all aspects the task, including unexpected situations and emergencies, and ensure suitable control measures are in place