



INCIDENT ALERT

General Information

Date of Incident: 5/5/1998

State: WA

Where in Work Place: Aluminium Refinery

Type of Incident: Equipment Damage

About the Person

Occupation of Person: HPWJ operator

Experience of Person: 2 – 5 Years

Training Level: Company Induction

Other Training: Company Internal Training

Number of Hours Completed: 4 – 6 hours

About the Incident

Time of Accident: 1:00pm

Result of Injury: Equipment Damage

Lost Days: Nil

Description of Incident: HP hose end snapped causing the tank cleaning head to swing about violently in the tank

What Equipment Category: Tank Cleaner

Equipment Used: Tank Cleaning Head

Corrective Action

What Happened Unexpectedly: HP hose end snapped causing the tank cleaning head to swing about violently in the tank

What was Person Doing: Descaling a process tank

What Immediate Action: The operation was suspended

What Preventative Action: Procedural review