



## **INCIDENT ALERT**

### **General Information**

**Date of Incident:** 06/01/2005

**State:** WA

**Where in Work Place:** Client refinery

**Type of Incident:** Potential Only

### **About the Person**

**Occupation of Person:** Operator

**Experience Of Person:** 12 - 24 Months

**Training Level:** Company Induction, Ausjet Basic Induction and Intermediate course

**Other Training:**

**Number of Hours Completed:** 4 - 6

### **About the Incident**

**Time of Accident:** 1000

**Result of Injury:**

**Lost Days:** 0

**Description of Incident:** The operators were working at 1000 bar when the hose blew. The hose had been inspected prior to starting the job and no braiding damage was evident.

**What Equipment Category:** Hose Nozzle

**Equipment Used:** 5 month old 1000 bar Spirstar hose

### **Corrective Action**

**What Happened Unexpectedly:** Hose blew out from ferrule. Upon inspection there was still some of the hose left inside the ferrule.

**What was Person Doing:**

**What Immediate Action:** Hose was tagged out and removed from service

**What Preventative Action:**