



INCIDENT ALERT

General Information

Date of Incident: 16/07/2006

State: WA

Where in Work Place: Off shore Rig

Type of Incident: First Aid

About the Person

Occupation of Person: HPWJ Operator

Experience of Person: More than 5 Years

Training Level: Company Induction, and Ausjet Basic Induction

Other Training:

Number of Hours Completed: 2 - 4

About the Incident

Time of Accident: 8am

Result of Injury: First Aid

Lost Days: 0

Description of Incident: Individual lost footing , causing the person to loose balance , system depressurized immediately grease nipple / nozzle struck the operators shoulder has the HP hose was extended .

What Equipment Category: Rotating Nozzle

Equipment Used: HP Gun

Corrective Action

What Happened Unexpectedly: Weight of HP hose caused the gun to recoil back thus the nozzle / Grease nipple coming around to the shoulder

What was Person Doing: UHP water jetting on a Caisson

What Immediate Action: First aid from the grease nipple or Nozzle there was no water injection

What Preventative Action: Add extra HP hose to Tumble box